

SERVICE ESTIMATE

VILLAGE OF ROMEOVILLE

Ship To: VILLAGE OF ROMEOVILLE Customer Contact: ROMEOVILLE

Customer PO: Need

Rush Truck Center, Joliet 103 S. Larkin Ave Joliet, IL 60436-1230 Repair Order #: 0052700267

Customer Advisor: Cavaucie Thurman

Date: 11/26/2025 Time: 1:33PM

Estimate #: 0052700216

Phone Number: 815-553-8300 Description: engine failure

THIS ESTIMATE IS SUBJECT TO THE RUSH TERMS AND CONDITIONS OF MAINTENANCE AND REPAIR SERVICES LOCATEDAT HTTPS://www.rushtruckcenters.com/rush-maintenance-and-repair-terms-of-service ("terms"). Customer confirms its agreements to the terms by authorizing the work set forth in this estimate. Any warranties on the products provided by rush are solely those made by the product manufacturer. Except for the limited services warranty set forth in the terms, rush expressly disclaims all warranties, express or implied, and rush neither assumes nor authorizes any other person to assume for it any liability in connection withany services provided or any products provided to customer in conjunction with the services.

Unit #:	VIN #:	Engine Serial:	Make/Model:
3	1HTWHAZT5FH667147	570HM2U3342081	7400:IH
Engine Make/Model:	Mileage:	Vehicle Year:	Engine Hours:
INTERNATIONAL	33,691	2015	2425

PERFORM STAGE 1 XPRESS CHECK

Complaint: PERFORM STAGE 1 XPRESS CHECK

Cause: engine failure
Correction: diag needed

Description	Part #	QTY/Hours	Core Charge	Total Cost	Status
PERFORM STAGE 1 XPRESS CHECK		1.00	\$0.00	\$227.00	Approved
DISABLE VEHICLE TOW-IN, ALLOWANCE		0.60	\$0.00	\$136.20	Approved

Job Summary					
Parts:	\$0.00	Coupon:	\$0.00	Shop:	\$39.95
Labor:	\$363.20	Ship:	\$0.00	Machine:	\$55.00
Misc:	\$0.00	EPA:	\$4.00	Tax:	\$0.00
				Job Total:	\$462.15

misfire cylinder 4

Complaint: misfire cylinder 4

Cause: kicked the rods out

Correction: replace engine

Description	Part #	QTY/Hours	Core Charge	Total Cost	Status
ENGINE ASSEMBLY (COMPLETE), REMOVE & REI		18.00	\$0.00	\$4,086.00	New

Description	Part #	QTY/Hours	Core Charge	Total Cost	Status
STRIPPED, SERVICE ENGINE PARTS, TRANSFER		4.90	\$0.00	\$1,112.30	New
HEAT, DRILL, AND/OR TAP BOLT/HOLES, REPA		10.00	\$0.00	\$2,270.00	New
CLAMP, HEAT EXCHANGER	3539142C1:IH	2.00	\$0.00	\$90.56	New
CLAMP, HOSE	3557856C1:IH	2.00	\$0.00	\$96.06	New
THERMOSTAT, TEMP REGULATOR	1842130C3:IH	1.00	\$0.00	\$110.35	New
HARDWARE, MOUNTING, RADIATOR,	2604166C92:IH	1.00	\$0.00	\$162.76	New
Bracket Lower Ltr Bracket (sho	2604167C91:IH	1.00	\$0.00	\$123.47	New
Bracket Lower Ltr Bracket (Ion	2604168C91:IH	1.00	\$0.00	\$135.56	New
Insulator, Engine Mounting, Re	3549169C3:IH	1.00	\$0.00	\$261.42	New
Insulator, Engine Mounting, Re	3549169C3:IH	1.00	\$0.00	\$261.42	New
INSULATOR, SNUBBER MOUNTING BO	3532955C1:IH	1.00	\$0.00	\$35.29	New
INSULATOR, SNUBBER MOUNTING BO	3532955C1:IH	1.00	\$0.00	\$35.29	New
Bolt M16 X 50 Mm	30752R2:IH	4.00	\$0.00	\$29.28	New
Bolt M16 X 50 Mm	30752R2:IH	4.00	\$0.00	\$29.28	New
Nut, Hex M16 Prvtrq	30756R1:IH	11.00	\$0.00	\$59.62	New
BOLT, FLANGE HEAD M16 X 9	40203R1:IH	2.00	\$0.00	\$20.88	New
Insulator, Engine Mount, Front	1664723C5:IH	2.00	\$0.00	\$49.80	New
Bolt, M16 X 100 Phc Class 10.9	31077R1:IH	2.00	\$0.00	\$21.48	New
INSULATOR, ENGINE MOUNT, REAR,	1664726C4:IH	2.00	\$0.00	\$57.40	New
Washer, Engine Mounting Bolt,	3564182C1:IH	2.00	\$0.00	\$29.96	New
Nut, Hex M16 Prvtrq	30756R1:IH	1.00	\$0.00	\$5.42	New
Trimmed Remanufactured Engine,	5010943R91:IH	1.00	\$4,256.00	\$29,706.00	New
COMPRESSOR, AIR, BRAKE, TF-550	BX5019321:IBW	1.00	\$559.93	\$1,345.73	New
THERMOPLASTIC HOSE CLAMP	2506705C1:IH	4.00	\$0.00	\$85.32	New
Cap, Filler, Radiator, Surge T	3578833C3:IH	1.00	\$0.00	\$33.99	New
FLEETRITE ENGINE DEGREASER	FLTAEDG16KK:IKK	2.00	\$0.00	\$9.34	New
MOBIL DELVAC 1ATF 668 (4/1 GAL JUG)	126980EXX:MBL	4.00	\$0.00	\$299.60	New
Sealant-5699 Gray Rtv	LOC18718KK:IKK	1.00	\$0.00	\$23.89	New
SENSOR, OIL PRESSURE, ICP/BCP	1875784C94:IH	1.00	\$0.00	\$159.96	New
FLUID GEL MED STRGTH BLUE 10G	PTX24010KK:IKK	1.00	\$0.00	\$14.19	New
BERRYMAN NON-CHLOR BRAKE CLEANER	2420:BRM	6.00	\$0.00	\$26.94	New
Cable Ti	BDTC24706:I27	50.00	\$0.00	\$5.00	New
BELT, FAN V- RIBBED 10- PACKAG	1847715C1:IH	1.00	\$0.00	\$70.15	New
MOBIL DELVAC HDEO 15W-40 (BULK QT)	125152EXX:MBL	32.00	\$0.00	\$223.68	New
ZX HD EXTENDED LIFE 50/50 AFC 6/1 GA	ZXEDRU1:VLV	12.00	\$0.00	\$107.88	New
Fleetrite Automatic Transmissi	FLTPSDX3QKK:IKK	4.00	\$0.00	\$32.40	New
ORING & GASKET KIT -NAVISTAR	790-1069:R51	1.00	\$0.00	\$34.90	New
Clamp, Exhaust	1893794C1:IH	1.00	\$0.00	\$21.71	New
Locknut, Hex, 1/4-28	1893799C1:IH	1.00	\$0.00	\$15.23	New
GASKET, EXHAUST PIPE FLANGE	2015983C1:IH	1.00	\$0.00	\$36.51	New
Clamp, V-band, Exhaust, W/ Qui	3869550C1:IH	1.00	\$0.00	\$48.33	New
Gasket, Exhaust Pipe Flange, 4	3900706C1:IH	1.00	\$0.00	\$33.50	New

Description	Part #	QTY/Hours	Core Charge	Total Cost	Status
Gasket, Mounting, Power Steeri	591597C2:IH	1.00	\$0.00	\$12.10	New
Gasket, Mounting, Air Compress	1836235C1:IH	1.00	\$0.00	\$40.30	New
Hose, Heater, 1/2 X 50	L2643505:IH	6.00	\$0.00	\$18.66	New
Hose, Air Compressor	1821023C1:IH	1.00	\$0.00	\$45.96	New
Tube	6084270C2:IH	1.00	\$0.00	\$315.43	New
THERMOPLASTIC HOSE CLAMP	2506705C1:IH	2.00	\$0.00	\$42.66	New

Job Summar	ry			25000	
Parts:	\$34,424.66	Coupon:	\$0.00	Shop:	\$597.46
Labor:	\$7,468.30	Ship:	\$0.00	Machine:	\$0.00
Misc:	\$0.00	EPA:	\$4.00	Tax:	\$0.00
				Job Total:	\$42,494.42

Estimate Summary							
Parts:	\$34,424.66	Coupon:	\$0.00	Shop:	\$637.41		
Labor:	\$7,831.50	Ship:	\$0.00	Machine:	\$55.00		
Misc:	\$0.00	EPA:	\$8.00	Tax:	\$0.00		

Estimate Total: \$42,956.57

Notes

SERVICES ESTIMATED TO BE \$5,000 OR MORE FOR A VEHICLE OLDER THAN 96 MONTHS (8 YEARS) MUST BE SECURED BY A DOWN PAYMENT OF NO LESS THAN 50% OF THE TOTAL VALUE OF THE ESTIMATED SERVICES.

Authorization of Charges. I represent that I am the owner, or am acting as a duly authorized agent of and have authority to bind, the owner (herein, "Owner") of the above-described vehicle (the "Vehicle"). Customer hereby authorizes the necessary diagnostic/repair work to be done including the supply of any necessary parts and material. Customer understands that any estimates are based on Rush's preliminary inspection and do not cover any additional parts/labor that may be required after the work has been started. Occasionally, worn or damaged parts are discovered that may not be evident on the first inspection. Because of this, estimated prices are not guaranteed and are subject to change. Customer promises to pay for any applicable diagnostic, disassembly and reassembly services and repair work, together with all charges for any necessary repairs (collectively, the "Charges"). In addition to any and all other legal remedies available to Rush, Customer authorizes and acknowledges an express mechanic's lien in favor of Rush on the Vehicle for all charges for repairs, including labor and parts, storage and/or towing. Customer understands that all charges are due and payable by Customer at the Rush location indicated above except as otherwise agreed in writing by the parties. Customer understands that the work performed by Rush may not be covered by warranty or extended services plan and that the manufacturer or extended service plan provider will be the one to make the final determination as to what work will be covered. Customer agrees to pay any charges that are not covered by a warranty or extended service plan.